

X-MET8000

SAFETY GUIDE

- **DO NOT FORCE ANY SHARP ITEMS AGAINST THE DETECTOR WINDOW**

Items like earrings can puncture the airlock if pressed with force. Damage of this kind is not covered under warranty and may result in a **large repair bill**.



- **COVER WITH LEAD TOP**

When using a travel stand, ensure the sensor is covered with the lead top to maximize safety for both the operator and those nearby from X-ray exposure.



- **AVOID SCANNING DIRECTLY ONTO BODY PARTS.**

To protect yourself from X-ray radiation, always operate at arm's length when not using the travel stand, and **avoid scanning directly onto your own or someone's body**.